

Lehigh Cement Company, Catskill, NY

**Illegal Leachate Discharge
April 23, 2008**



Photo by Giles Ashford for Riverkeeper, Inc.

**Illegal Leachate Discharge
April 23, 2008**



Photo by Giles Ashford for Riverkeeper, Inc.

**Northern Wetland Pond
May 14, 2008**



Earthen dam forms edge of Northern pond

Water in Northern pond

Water from Northern pond flows into wetlands

Photo by Riverkeeper, Inc.